


Conexión de cable a cable

Conexiones con derivación en paralelo PC

Calibre del cable		
De paso	Derivación	Carga
6 Alam	6 Alam	25
6	6	25
	4	32
4	6	32
	6 Alam	32
	8 Alam	32
2 Alam	6 Alam	32
	6	32
	2 Alam	65
	2	65
	1/0	65
	2/0	65
2	2	65
	4	45
	6	32
	6 Alam	32
	8 Alam	32
1	2	65
	4	45
	6	45
	6 Alam	45
	8 Alam	45



Calibre del cable		
De paso	Derivación	Carga
	2	65
	4	65
1/0	6	45
	6 Alam	45
	8 Alam	45
2/0	2	90
	4	65
	6	65
	6 Alam	65
	8 Alam	65
4/0	1	115
	2	115
	4	90
	6	90
	6 Alam	90
	8 Alam	90